

LOUISIANA UNIFORM CRASH REPORT
CRASH INFORMATION

Rev. 2023-2

Case #

24-230073

Page 1 of 9

Secondary Crash, Photos Taken, Videos Taken
Number of Motorists 1, Number of Non-Motorists 0, Non-Fatally Injured Persons 0, Fatalities 0, Total Injuries and Fatalities 0, Vehicles Involved 1, Troop A
Investigating Agency: Baton Rouge PD, Division: East Baton Rouge, City: Baton Rouge, Latitude: 30.425235° N, Longitude: 91.159496° W

CRASH TIME INFORMATION

Crash Date/Time: 07/18/2024 2324, Police Notified Date/Time: 07/18/2024 2325, Police Arrived Date/Time: 07/18/2024 2330, Roadway Cleared Date/Time: 07/19/2024 0015, On Scene Investigation Completed Date/Time: 07/19/2024 0010

ROAD INFORMATION

Highway: Interstate 10, Road: 15647 INTERSTATE 10 ST
Distance/Direction From Intersection: 300.0 ft West, Intersecting Road: PERKINS RD

LOCATION INFORMATION

Road Classification: 100, Road Subtype: 200, Property Ownership: 100, Trafficway Characteristics: 100, Number of Intersection Approaches: 1, Traffic Flow Direction: W

INVESTIGATING OFFICER

Rank: Lt, First Name: TODD, Middle Name: , Last Name: WEBB, Suffix:
Badge #: P213, Printed Name: LT Todd Webb, Signature: LT Todd Webb

CRASH CIRCUMSTANCES AND CONDITIONS

First Harmful Event: 311, Location of First Harmful Event: 108, Manner of Crash: 000
Non-Collision: 100 Cargo/equipment loss or shift, 101 Fell/jumped from motor vehicle, 102 Fire/explosion, 103 Immersion, full or partial, 104 Jackknife, 105 Overturn/rollover, 106 Thrown or falling object, 198 Other non-collision harmful event
Collision with Non-Fixed Object: 200 Collision with animal (live), 201 Collision with motor vehicle in transport, 202 Collision with parked motor vehicle, 203 Collision with pedalcycle (including bicycles), 204 Collision with pedestrian, 205 Collision with railway vehicle (train, engine), 206 Collision with object at rest from MV in transport, 207 Collision with falling/shifting cargo or anything set in motion by MV, 208 Collision with work zone/maintenance equipment, 209 Collision with farm equipment, 297 Collision with other non-motorist, 298 Collision with other non-fixed object
Collision with Fixed Object: 300 Collision with bridge overhead structure, 301 Collision with bridge pier or support, 302 Collision with bridge rail, 303 Collision with cable barrier, 304 Collision with concrete traffic barrier, 305 Collision with culvert, 306 Collision with curb, 307 Collision with ditch, 308 Collision with embankment, 309 Collision with fence, 310 Collision with guardrail end terminal, 311 Collision with guardrail face, 312 Collision with impact attenuator/crash cushion, 313 Collision with mailbox, 314 Collision with traffic sign support, 315 Collision with traffic signal support, 316 Collision with tree (standing), 317 Collision with utility pole/light support, 396 Collision with other post, pole, or support, 397 Collision with other traffic barrier, 398 Collision with other fixed object (wall, building, tunnel, etc.), 399 Collision with unknown fixed object
Relation to Junction: 000, Contributing Factor: Primary 103, Secondary 101
Intersection Geometry: 970, School Bus Relation: 000
Intersection Traffic Control: 970

LOUISIANA UNIFORM CRASH REPORT CRASH INFORMATION

Rev. 2023-2

Case # 24-230073 Page 2 of 9

CRASH CONDITIONS

Roadway Surface Condition 000 Dry 100 Ice/Frost 101 Mud, dirt, gravel 102 Oil 103 Sand 104 Slush 105 Snow 106 Water (standing,moving) 107 Wet 980 Other 999 Unknown	Light Condition 100 Daylight 200 Dawn/dusk 300 Dark - continuous street lights 301 Dark - street lights at intersection only 302 Dark - not lighted 399 Dark - unknown lighting 980 Other 999 Unknown	Weather Conditions 000 Clear 100 Blowing sand, soil, dirt 101 Blowing snow 102 Cloudy 103 Fog, smog, smoke 104 Freezing rain or freezing drizzle 105 Rain 106 Severe crosswinds 107 Sleet or hail 108 Snow 980 Other 999 Unknown	Environmental Conditions 000 None 100 Animal(s) 101 Debris 102 Glare 103 Non-highway work 104 Obstructed crosswalks 105 Obstruction in roadway 106 Overhead clearance limited 107 Prior crash 108 Prior non-recurring incident 109 Regular congestion 110 Related to a bus stop 111 Road surface condition (wet, icy, snow, slush, etc.)	Environmental Conditions 112 Ruts, holes, bumps 113 Shoulders (none, low, soft, high) 114 Toll booth/plaza related 115 Traffic control device 116 Traffic incident 117 Visual obstruction(s) 118 Weather conditions 119 Work zone (construction/maintenance/utility) 120 Worn, travel-polished surface 980 Other 999 Unknown
---	--	---	--	--

WORK ZONE CRASH INFORMATION

Work Zone Relation 000 No 100 Yes 999 Unknown	Work Zone Location 100 Before the first work zone warning sign 101 Advance warning area 102 Transition area 103 Activity area 104 Termination area 970 Not applicable 999 Unknown	Work Zone Type 100 Lane closure 101 Lane shift / crossover 102 Work on shoulder or median 103 Intermittent or moving work 970 Not applicable 980 Other type of work zone 999 Unknown	Work Zone Circumstances 100 Back of queue 101 Congestion (dense & slow traffic), typical 102 Heavy (dense & fast traffic) 103 Congestion (dense & slow traffic), not typical 104 Traffic control device malfunction 105 Free flow (light & fast traffic) 980 Other 970 Not applicable 999 Unknown	Worker(s) Present 000 No 100 Yes 970 Not applicable 999 Unknown	Law Enforcement Present 000 No 100 Yes 970 Not applicable 999 Unknown
---	---	--	---	--	--

REVIEWING OFFICER

Rank	First Name HAROLD	Middle Name	Last Name POURCIAU	Suffix
-------------	-----------------------------	--------------------	------------------------------	---------------

WITNESS #		WITNESS #	
Name	Name	Name	Name
First Middle Last Suffix	First Middle Last Suffix	First Middle Last Suffix	First Middle Last Suffix
Address	Address	Address	Address
City State Postal Code	City State Postal Code	City State Postal Code	City State Postal Code
Phone Number	Age	Sex	Phone Number
Age Sex	Age Sex	Age Sex	Age Sex

NON-VEHICULAR PROPERTY DAMAGE

PROPERTY #

Property Type	Damage Severity	Owner Name <input type="checkbox"/> Unknown	Owner Phone Number <input type="checkbox"/> Not Collected
Owner Address <input type="checkbox"/> Unknown			
Street	City	State	Postal Code

NON-VEHICULAR PROPERTY DAMAGE

PROPERTY #

Property Type	Damage Severity	Owner Name <input type="checkbox"/> Unknown	Owner Phone Number <input type="checkbox"/> Not Collected
Owner Address <input type="checkbox"/> Unknown			
Street	City	State	Postal Code

NON-VEHICULAR PROPERTY DAMAGE

PROPERTY #

Property Type	Damage Severity	Owner Name <input type="checkbox"/> Unknown	Owner Phone Number <input type="checkbox"/> Not Collected
Owner Address <input type="checkbox"/> Unknown			
Street	City	State	Postal Code

PROPERTY DAMAGE CODES

Property Type	Damage Severity
100 Private property 200 Bridge overhead structure 201 Bridge pier or support 202 Bridge rail	300 Cable barrier 301 Concrete traffic barrier 302 Guardrail end terminal 303 Guardrail face 304 Impact attenuator/crash cushion 398 Other traffic barrier 400 Traffic sign support 401 Traffic signal support 402 Utility pole/light support 598 Other state property 980 Other
	100 Light (less than \$500) 101 Moderate (between \$500 and \$10,000) 102 Severe (over \$10,000)

LOUISIANA UNIFORM CRASH REPORT VEHICLE INFORMATION

Motor Vehicle # 1 Case # 24-230073 Page 3 of 9

DESCRIPTION AND INFORMATION

Check if this vehicle had no driver Hit and Run Vehicle Type Vehicle Body Type VIN 1GNFC16078J247883 Model Year 2008 Make Chevrolet Model Suburban Color Blue, dark License Plate MH015129 Owner Name prentiss I bellue III Owner Address 12194 CANE DR ST FRANCISVILLE LA 70775 Insurance Company USAA Phone # 210-531-8722 NAIC # 25968 Policy # 029752464C Expiration Date

DAMAGE

TOWING

Damage Extent 102 Initial Point of Contact Damaged Areas Tow Status 101 Tow Authority 101 Towed By Unknown Roadrunner Towing

MOTOR VEHICLE CIRCUMSTANCES

Vehicle Usage 000 Vehicle Maneuver 111 Vehicle Maneuver Reason 206 Emergency Vehicle Usage 970 Direction of Travel Before Crash 700

LOUISIANA UNIFORM CRASH REPORT VEHICLE INFORMATION

Motor Vehicle # 1 Case # 24-230073 Page 4 of 9

MOTOR VEHICLE CIRCUMSTANCES

Skidmark Data (Feet) Distance Traveled After Impact (Feet) Contributing Defects Vehicle Lighting Traffic Control Device Types and Statuses

Trafficway Division Barrier Type

Roadway Grade Number of Through Lanes Number of Auxiliary Lanes Roadway Alignment Permitted Travel Speed Limit HOV Lane Presence HOV Lane Relation

MOTOR VEHICLE EVENTS

Sequence of Events 1 006 2 311 3 4 Most Harmful Event 311

Non-Harmful Events Collision with Fixed Object

Non-Collision Events Collision with Person / Vehicle / Non-Fixed Object

LOUISIANA UNIFORM CRASH REPORT VEHICLE INFORMATION

Motor Vehicle #
1

Rev. 2023-2

Case # 24-230073 Page 5 of 9

COMMERCIAL MOTOR VEHICLE INFORMATION

Vehicle Configuration		000	Hazardous Materials Placard	000
000 Vehicles 10,000 lbs or less	300 Single-unit truck (2-axle and GVWR > 10,000 lbs.)	999 Unknown	000 Had no placard and not carrying hazardous materials	
100 Vehicles 10,000 lbs or less placarded for hazardous materials	301 Single-unit truck (3 or more axles)		001 Had a placard, not carrying hazardous materials	
200 Bus/large van (seats 9-15 occupants, including driver)	302 Truck pulling trailer(s)		100 Carried hazardous material that required placarding	
201 Bus (seats more than 15 occupants, including driver)	303 Truck tractor (bobtail)		200 Carried hazardous materials without placard	999 Unknown
	304 Truck tractor/semi-trailer		Hazardous Material ID	N/A
	305 Truck tractor/double		Hazardous Material Class	970
	306 Truck tractor/triple		1 Explosives	970 Not applicable
	307 Truck more than 10,000 lbs., cannot classify		2 Gas	999 Unknown

Cargo Body Type		970	Special Sizing	
000 No cargo body			<input checked="" type="checkbox"/> 000 No special sizing	
100 Bus	105 Flatbed	109 Log	<input type="checkbox"/> 100 Over-height	
101 Auto transporter	106 Garbage / refuse	110 Pole trailer	<input type="checkbox"/> 101 Over-length	
102 Cargo tank	107 Grain / chips / gravel	111 Van / enclosed box	<input type="checkbox"/> 102 Over-weight	
103 Concrete mixer	108 Intermodal container chassis	112 Vehicle towing another vehicle	<input type="checkbox"/> 103 Over-width	
104 Dump			<input type="checkbox"/> 999 Unknown	
970 Not applicable	980 Other	999 Unknown		
			Hazardous Materials Released from Vehicle Cargo Compartment	
			000 No, hazardous materials not released	
			100 Yes, hazardous materials released	
			970 Not applicable	

Load Permitted	970	Number of Axles	<input type="checkbox"/> Unknown	Motor Carrier Type	000	Motor Carrier Identification	970
000 Non-permitted load				000 Personal vehicle		100 US DOT number	
100 Permitted load				001 Not in commerce: government		101 State number	
970 Not applicable (not a qualifying vehicle)				002 Not in commerce: personal rental truck or bus		970 Not applicable	
999 Unknown				098 Not in commerce: other		999 Unknown/unable to determine	
				100 Interstate carrier		State	
				101 Intrastate carrier			
						Motor Carrier Name	<input type="checkbox"/> Unknown
						Motor Carrier ID Number	

Motor Carrier Address	<input type="checkbox"/> Unknown	Motor Carrier Phone Number	<input type="checkbox"/> Unknown
Street	City	State	Postal Code

GVWR/GCWR	100	Commodity Hauled
100 Light (less than 10,000 lbs.GVWR/GCWR)		
101 Medium (10,001 - 26,000 lbs GVWR/GCWR)		
102 Heavy (greater than 26,000 lbs GVWR/GCWR)		
970 Not applicable (not a qualifying vehicle)		
999 Unknown		

TRAILER INFORMATION			TRAILER #
VIN	<input type="checkbox"/> Unknown	Number of Axles	<input type="checkbox"/> Unknown
Year	<input type="checkbox"/> Unknown	Make	<input type="checkbox"/> Unknown
		Model	<input type="checkbox"/> Unknown
License Plate	<input type="checkbox"/> Missing	<input type="checkbox"/> Non-expiring	
State	<input type="checkbox"/> Unknown	Number	<input type="checkbox"/> Unknown
		Year	<input type="checkbox"/> Unknown

TRAILER INFORMATION			TRAILER #
VIN	<input type="checkbox"/> Unknown	Number of Axles	<input type="checkbox"/> Unknown
Year	<input type="checkbox"/> Unknown	Make	<input type="checkbox"/> Unknown
		Model	<input type="checkbox"/> Unknown
License Plate	<input type="checkbox"/> Missing	<input type="checkbox"/> Non-expiring	
State	<input type="checkbox"/> Unknown	Number	<input type="checkbox"/> Unknown
		Year	<input type="checkbox"/> Unknown

TRAILER INFORMATION			TRAILER #
VIN	<input type="checkbox"/> Unknown	Number of Axles	<input type="checkbox"/> Unknown
Year	<input type="checkbox"/> Unknown	Make	<input type="checkbox"/> Unknown
		Model	<input type="checkbox"/> Unknown
License Plate	<input type="checkbox"/> Missing	<input type="checkbox"/> Non-expiring	
State	<input type="checkbox"/> Unknown	Number	<input type="checkbox"/> Unknown
		Year	<input type="checkbox"/> Unknown

LOUISIANA UNIFORM CRASH REPORT DRIVER INFORMATION

Motor Vehicle # 1 Case # 24-230073 Page 6 of 9

DRIVER INFORMATION

Name: [] Unknown, Age: 51, Sex: 101 Female, Race: 103 American Indian or Alaska Native, Address: 12194 CANE DR ST FRANCISVILLE LA 70775, Date of Birth: 8/25/1972

DRIVER LICENSE INFORMATION

License Status: 100 Valid license, License Class: 400 Regular driver license, Driver License Type: 100 Non-CDL driver license, Commercial Driver License Status: 970 Not applicable

Endorsements on License: [x] 200 M - Motorcycle, Endorsement Compliance: 000 No endorsements required, Restrictions on License: 000 - None, Alcohol Interlock Presence: 970 Not applicable

DRIVER SEATING AND SAFETY INFORMATION

Seating Position: 100 Standard Vehicle Seats, Restraint Systems Used: 001 None used - motor vehicle occupant, 002 No helmet, 970 Not applicable

Air Bags Deployed: [x] 100 Front, Ejection: 000 Not ejected, Extrication: 000 No

LOUISIANA UNIFORM CRASH REPORT DRIVER INFORMATION

Motor Vehicle # 1	Rev. 2023-2	Case # 24-230073	Page 7	of 9
-----------------------------	-------------	-------------------------	---------------	-------------

MEDICAL INFORMATION			
Injury Status 104	Type of Medical Transportation 000	EMS Response Agency	
100 (K) Fatal Injury 101 (A) Suspected Serious Injury 102 (B) Suspected Minor Injury 103 (C) Possible Injury 104 (O) No Apparent Injury	000 Not transported 100 EMS air 101 EMS ground 200 Law enforcement 980 Other 999 Unknown	Not applicable	
Medical Unique Identifier <input checked="" type="checkbox"/> Not applicable <input type="checkbox"/> Unknown		Facility Receiving Patient	
		Not applicable	

DRIVER CONDITION AND CIRCUMSTANCES					
Conditions at Time of Crash 105	Distraction Action 980	Distraction Source 101	Speeding Relation 000		
000 Apparently normal 100 Asleep/blacked out 101 Fatigued 102 Emotional (depressed, angry, disturbed, etc.) 103 Ill (sick), fainted 104 Physically impaired 105 Under the influence of medications/drugs/alcohol 106 Inattentive/distracted 970 Not applicable 980 Other 999 Unknown	000 Not distracted 100 Talking / listening 101 Manually operating a device (e.g., texting, dialing, playing game, etc.) 200 Inattentive 980 Other distraction 999 Unknown distraction	100 Hands-free mobile phone 101 Hand-held mobile phone 102 Vehicle-integrated device 198 Other electronic device 970 Not applicable 999 Unknown Vision Obscurement 000 None 100 Rain, snow, etc. on windshield 101 Windshield otherwise obscured 102 Vision obscured by load 103 Trees, bushes, etc. 104 Building 200 Passenger or other non-motorist 201 External to vehicle/non-motorist area 298 Other 970 Not applicable 999 Unknown 105 Embankment 106 Sign boards 107 Hillcrest 108 Parked vehicles 109 Moving vehicles 110 Blinded by headlights 111 Blinded by sun glare 112 Distracted by neon lights in field of view 980 Other 999 Unknown	000 No 100 Exceeded speed limit 101 Racing 102 Too fast for conditions 999 Unknown		
Suspected Alcohol Usage 100	Test Status 100	Alcohol Kit Number <input checked="" type="checkbox"/> Unknown	Alcohol Test Type 200	Alcohol Test Results 100	BAC 0.137
000 No 100 Yes 999 Unknown	000 Test not given 001 Test refused 100 Test given 999 Unknown if tested		100 Blood 101 Blood clot 102 Blood plasma/serum 200 Breath 201 Preliminary breath test (PBT) 300 Urine 301 Vitreous 302 Liver 970 Not applicable 980 Other	000 Results pending 001 Negative results with no actual value 100 Results received 101 Positive results with no actual value 970 Not applicable 999 Unknown	
Suspected Drug Usage 000	Test Status 000	Drug Kit Number <input type="checkbox"/> Unknown	Drug Test Type 970	Drug Test Results	
000 No 100 Yes 999 Unknown	000 Test not given 001 Test refused 100 Test given 999 Unknown if tested		100 Blood 101 Urine 102 Both blood and urine 103 Saliva 198 Other 970 Not applicable 999 Unknown	Not applicable	

DRIVER ACTIONS		
Driver Actions at Time of Crash 109	Avoidance Maneuver 999	Pre-Collision Stability 999
000 No contributing action 100 Disregarded other road markings 101 Disregarded other traffic signs 102 Failed to keep in proper lane 103 Failed to yield right-of-way 104 Followed too closely 105 Improper backing 106 Improper passing 107 Improper turn 108 Operated motor vehicle in inattentive, careless, negligent, or erratic manner 109 Operated motor vehicle in reckless or aggressive manner 110 Over-correcting or over-steering 111 Ran off roadway 112 Ran red light 113 Ran stop sign 114 Swerved or avoided due to wind, slippery surface, motor vehicle, object, non-motorist in roadway, etc. 115 Wrong side or wrong way 980 Other contributing action 999 Unknown	000 No avoidance maneuver 100 Accelerating 101 Accelerating and steering left 102 Accelerating and steering right 103 Braking and steering left 104 Braking and steering right 105 Braking (lockup) 106 Braking (no lockup) 107 Braking (lockup unknown) 108 Releasing brakes 109 Steering left 110 Steering right 980 Other 999 Unknown	000 Tracking 100 Skidding longitudinally - rotation less than 30 degrees 200 Skidding laterally - clockwise rotation 201 Skidding laterally - counter-clockwise rotation 299 Skidding laterally - rotation direction unknown 980 Other vehicle loss of control 999 Unknown

CITATIONS

DIAGRAM

Rev. 2023-2

Scene #

1

Case #

24-230073


Page

8

of

9

CRASH DIAGRAM




Final rest

Year 2008
Make CHEVROLET
Model Suburban



Year 2008
Make CHEVROLET
Model Suburban



15647 W I 10

LOUISIANA UNIFORM CRASH REPORT
NARRATIVE

Rev. 2023-2

Case # 24-230073 Page 9 of 9

CRASH NARRATIVE

On listed date and time, while working the quick reaction force extra duty for crashes, I heard a crash go out on the radio in the area of W I 10 near Perkins. I proceeded to the area in order to work the crash.

Prior to my arrival, several uniform patrol units had arrived on scene. I arrived on scene and contacted Ofc. Herbert Allen, who stated that he had initially contacted the driver of Veh 1 and he believed that the driver was intoxicated. Ofc. Allen had called for a DWI unit to respond. Driver of Veh 1 was already detained and in the back seat of a patrol unit. Due to this being a criminal investigation I did not question driver of Veh 1. Veh 1 was incapacitated with heavy front end damage.

Roadrunner arrived and towed Veh 1. As soon as the roadway was cleared we moved to Dalrymple Dr to await the DWI officers arrival.

Sgt Scott Johnson arrived on scene and conducted his DWI investigation (see his report under this file).

The following officers were also on scene

- Sidney Williams
- Damien Collins
- James Thomas
- LT Troy McCreary

Nothing Follows

=====
 =====
 Disclaimer: All information below this line is auto-generated from report data.
 =====
 =====

Vehicle 1 Driver Distraction Action: DROPPED CELL PHONE